

In the specification:

Page 8, third paragraph in lines 15-18, amend as follows:

*C 2*

~~As can be seen from the drawings, one of the pistons has a second piston rod. The housing has a rod 20 which extends to the right/left and has the same diameter as the piston rod 9 of the piston 8, to assure that both pistons 5 and 8 have the same piston area areas 21 and 22 correspondingly at the right side.~~

*X*